

## Part List

- mechanical -



*Xperia™ T3, Xperia™ Style  
D5102, D5103, D5106, M50w*



make.believe  
*Part List Mechanical/*

**CONTENTS**

**1    Part List ..... 3**  
**2    Revision History ..... 11**













## 1 Part List




The following parts are available for order in 'E-star'.

















The 'E-star' name of a part may often be complex and even confusing, so the name of certain parts mentioned in the Working Instructions, Repair Movies and Troubleshooting Guide are often referred to by a simple descriptive name for better understanding.













Both names (designations) will in that case be included in this Part List, where the name being used in the documents mentioned above is underlined, e.g. Battery Cover.

















RLC, Reversed Logistic Classification column for replaced part handling, See the Spare part handling chapter in Mechanical/Generic Repair Manual (1220-1333).

















| Designation             | Part No.      | RLC | Part  | Location  |
|-------------------------|---------------|-----|---|---|
| Adhesive Tape Battery 1 | F/56BGUL00010 | C   |    |    |
| Adhesive Tape Battery 2 | F/56BGUL00017 | C   |   |   |
| Adhesive Tape Battery 3 | F/56BGUL00022 | C   |   |  |
| Adhesive Tape FPC       | F/56BGUL00019 | C   |  |  |
| Adhesive Tape Vibrator  | F/56BGUL00011 | C   |  |  |
| Antenna BT & WIFI       | F/80012280334 | C   |   |  |

| Designation  | Part No.  | RLC | Part  | Location  |
|--|---|-----|---|---|
| Antenna Diversity  | F/80012280330                                   | C   |    |    |
| <u>Antenna FPC</u><br>Antenna FPC LTE Americas<br>Antenna FPC LTE ROW<br>Antenna FPC WCDMA                 | F/312GUL12C1C<br>F/312GUL12C0D<br>F/312GUL12C2C | C   |     |    |
| Antenna GPS  | F/80012280331                                   | C   |     |    |
| <u>Antenna Main RF</u><br>Antenna Main RF LTE Americas<br>Antenna Main RF LTE ROW<br>Antenna Main RF WCDMA | F/80012280333<br>F/80012280335<br>F/80012280332 | C   |    |   |
| Antenna Spring 1   | F/440MAD0860A                                   | C   |  |  |
| Antenna Spring 2   | F/440MAD0960A                                   | C   |   |  |
| Audio Jack Mylar   | F/464GUL00112                                   | C   |  |  |
| Battery 2500 mAh   | 1278-2168.1                                     | B   |   |  |











| Designation  | Part No.  | RLC | Part  | Location  |
|--|---|-----|---|---|
| <u>Battery Cover</u><br><br>Battery Cover Black<br>Battery Cover Purple<br>Battery Cover White             | F/196GUL0001A<br>F/196GUL0004A<br>F/196GUL0002A | B   |     |    |
| Bracket Cable Assy   | F/440GUL20Z0A                                   | C   |     |    |
| Bracket Side Key   | F/440GUL19Z0A                                   | C   |     |    |
| Camera 8MP   | F/475NIK0510A                                   | B   |   |   |
| Camera Chat  | F/475GUL0000A                                   | C   |   |  |
| Core Unit Label  | F/2501125100A                                   | C   |  |  |
| Ear Speaker  | F/79626087000                                   | C   |  |  |
| <u>Front Cover Assy</u><br><br>Front Cover Assy Black<br>Front Cover Assy Purple<br>Front Cover Assy White | F/191GUL0005A<br>F/191GUL0007A<br>F/191GUL0006A | A   |   |  |









| Designation        | Part No.      | RLC | Part  | Location  |
|--------------------|---------------|-----|---|---|
| Gasket Cable       | F/56EGUL00007 | C   |    |    |
| Gasket Camera Main | F/56EGUL00003 | C   |    |    |
| Gasket Ear Speaker | F/56EGUL00002 | C   |    |    |
| Gasket Loudspeaker | F/56EGUL00004 | C   |  |   |
| Gasket Shielding 1 | F/56EGUL00006 | C   |  |  |
| Gasket Shielding 2 | F/56EGUL00001 | C   |  |  |
| Gasket Spring      | F/56FGUL00000 | C   |  |  |
| Gasket Vibrator    | F/56DGUL00009 | C   |  |  |

| Designation   | Part No.   | RLC | Part  | Location  |
|---|--|-----|---|---|
| Kapton Bracket  | F/464GUL00110  | C   |    |    |
| Kapton Connector  | F/56DGUL00023  | C   |     |    |
| <u>Label Tray CU</u><br>Label Tray CU-China<br>Label Tray CU-LTE Americas<br>Label Tray CU-LTE ROW<br>Label Tray CU-WCDMA | F/56BGUL00018<br>F/56BGUL00034<br>F/56BGUL00033<br>F/56BGUL00035 | C   |     |    |
| Link FPC  | F/312GUL24C0D  | C   |    |   |
| Liquid Indicator 1  | F/2501119300A  | C   |  |  |
| Liquid Indicator 2  | F/2501123100A  | C   |  |  |
| Loudspeaker   | F/79100071000  | C   |  |  |
| Mylar Camera Main   | F/464GUL00102  | C   |  |  |

| Designation            | Part No.      | RLC | Part  | Location  |
|------------------------|---------------|-----|---|---|
| Mylar USB              | F/464GUL00107 | C   |    |    |
| RF Cable               | F/2802001300A | C   |     |    |
| Rubber Camera Chat     | F/450GUL0110A | C   |    |    |
| Rubber Gasket Flash    | F/455GUL0410A | C   |  |   |
| Rubber Gasket Mic 2nd  | F/455GUL0210A | C   |  |  |
| Rubber Gasket Mic Main | F/455GUL0110A | C   |  |  |
| Rubber Indicator       | F/56DGUL00021 | C   |  |  |
| Rubber Proximity       | F/455GUL0010A | C   |  |  |



| Designation  | Part No.  | RLC | Part  | Location  |
|--|---|-----|---|---|
| Screw FPH(T5)M1.2 x 2.4  | F/50001202430                                   | C   |    |    |
| Sheet Brittle Label  | F/2501123200A                                   | C   |    |    |
| <u>SIM-SD Cap</u><br>SIM-SD Cap Black<br>SIM-SD Cap Purple<br>SIM-SD Cap White | F/460GUL00108<br>F/460GUL00Z04<br>F/460GUL00504 | C   |     |    |
| Speaker Sponge   | F/56DGUL00010                                   | C   |   |   |
| Spring Grounding   | F/440MAD1060A                                   | C   |  |  |
| Tape BT & WiFi Antenna   | F/56BGUL00031                                   | C   |  |  |
| Tape Camera Main 1   | F/56DGUL00007                                   | C   |  |  |
| Tape Camera Main 2   | F/56DGUL00008                                   | C   |  |  |

| Designation            | Part No.      | RLC | Part  | Location   |
|------------------------|---------------|-----|---|--|
| Tape Diversity Antenna | F/56BGUL00039 | C   |  |   |
| Thermal Pad 1          | F/56ZGUL00000 | C   |  |   |
| Thermal Pad 2          | F/56ZGUL00001 | C   |   |   |
| Vibrator               | F/79508VM1001 | C   |  |  |

## 2 Revision History

| Rev. | Date         | Changes / Comments                                    |
|------|--------------|---|
| 1    | 2014-June-27 | Released  |
| 2    | 2014-July-08 | No update, system migration issue                     |
| 3    | 2014-Aug-12  | Label Tray PN update for CU-LTE Americas & CU-LTE ROW |
| 4    | 2014-Sep-26  | Mylar USB New Part Added                              |
| 5    | 2014-Sep-26  | No update, system migration issue                     |